

BRUCE B. CLARK, P.E.
CONSULTING ENGINEER
75 East Main Street
Gouverneur, NY 13642-1036
(315) 287-2525, fax 287-2595
E-Mail: bbclark@northnet.org

May 3, 2000

APPENDIX b: COST ESTIMATE

Repairs Necessitated By Poor Workmanship				
1. Site Work				
	A.	Establish Finish Grade In Accordance With Contract Drawings	\$1,040.00	
	В.	Repair Of Waterproofing Membrane	\$500.00	
	C.	Repair Septic System (Already Complete)	\$3,900.00	
2.	Fo	oundations		
	A.	Remove And Replace Basement Slab. (Includes Radiant Heating)	\$25,559.00	
	B.	Install New Piers Under Entryway	\$856.00	
3.	Fra	Framing		
	A.	Remove And Replace Floor Decking. (Includes Leveling And Jacking)	\$10,485.00	
	B.	Remove And Replace Existing Stairs. (New Stairs To Be Oak Treads & Risers)	\$5,991.00	
	C.	Miscellaneous Framing Of Walls (Includes Sheetrock)	\$2,510.00	
4.	Ro	Roofing		
	A.	Remove And Install New Roofing System In Accordance With Contract Drawings	\$4,320.00	
		Diawings		
5.	Sh	Sheathing And Siding		
	A.	Remove And Replace Existing Sheathing And Siding	\$12,967.00	
6.	Me	echanical		
	A.	Reroute Exhaust Vent For Oil-Fired Boiler. (Thru Basement Wall)	\$3,600.00	
	B.	Install Heating In Entryway And Garage Attic	\$3,200.00	
	C.	Miscellaneous Plumbing Repairs	\$1,800.00	

7. Electrical

A. Miscellaneous Electrical Tasks & Repairs

\$4,200.00

Total: \$80,928.00

15% Contingency: <u>\$12,139.20</u>

Project Total: \$93,067.20